


[CAREERS](#)
[DEALER ACCESS](#)
[FEEDBACK](#)


[PRODUCTS](#)
[INDUSTRIES](#)
[SOLUTIONS](#)
[TECH TALK](#)
[SUPPORT](#)
[ABOUT US](#)
[CONTACT US](#)


[Or Browse by Topic](#)

(Solutions, White Papers, Case Studies, Technical Papers, Manuals, etc.)

[Support » SPAN® on OEM615 Dual-Frequency GNSS/INS Receiver](#)
[Log a Support Case ▶](#)
[Support Login ▶](#)

SPAN® on OEM615 Dual-Frequency GNSS/INS Receiver

This is a previous generation product

▼ DETAILS

Effective April 21, 2017, NovAtel Announces End Of Life of the OEM615 board

These products will be available for order until:

September 29, 2017 (or until inventory is depleted)

Shipments may be scheduled for no later than:

March 30, 2018

NovAtel will continue to support and repair these products until:

September 30, 2020

For a complete list of affected part numbers and the associated replacement part numbers, please refer to the table below:

Discontinued Part Number	Replacement Part Number
OEM615-xxx-xxx-xxx	OEM719-
OEM615A-xxx-xxx-xxx	OEM719A-
OEM615B-xxx-xxx-xxx	OEM719B-
OEM615C-xxx-xxx-xxx	OEM719C-
OEM615V-xxx-xxx-xxx	OEM719-

Manuals

OEM6® Firmware Reference Guide	OM-20000129	REV 12 (2017-08-11)	PDF (4.1 MB)
▶ NOTES			
SPAN® on OEM6 User Manual	OM-20000139	REV 12 (2017-02-22)	PDF (7.5 MB)
Universal IMU Controller Quick Start Guide	GM-14915134	REV 2 (2017-02-22)	PDF (337 KB)
SPAN® on OEM6 Firmware Reference Manual	OM-20000144	REV 8 (2017-01-05)	PDF (1.6 MB)
SPAN® on OEM6 Quick Start Guide	GM-14915112	REV 9 (2017-01-05)	PDF (795 KB)
MEMS Interface Card Quick Start Guide	GM-14915118	REV 5 (2017-01-05)	PDF (524 KB)
OEM6® Installation and Operation User Manual	OM-20000128	REV 12 (2016-11-01)	PDF (6.4 MB)

Product Sheets

OEM615™ Product Sheet	D16170	REV 8 (2015-11-30)	PDF (142 KB)
-----------------------	--------	--------------------	--------------

Firmware Downloads

SPAN OEM6.631 Firmware	VER 6.631 (2017-01-10)	ZIP (17 MB)
------------------------	------------------------	-------------

Training Videos

Basic SPAN Setup and Alignment	watch
--------------------------------	-------

Application Notes

Configure CAN for SPAN® Application Note	APN-046	REV 2D (2015-03-11)	PDF (407 KB)
Vehicle to Body Rotations Application Note	APN-037	(2015-02-25)	PDF (115 KB)

Connect Software

NovAtel Connect	VER 2.2.1 (2018-04-09) NEW	ZIP (56 MB)
	► NOTES	